









































































































 Attach the sensors to port 1-4
Attach the motors to port A-D

101

52